

General Administration Section, CO, Ranchi 4th Floor, Kaushalya Chambers, P P Compound, Main Road, Ranchi PIN - 834001. Phone: (91) (0651)-2330601, Mob no-9771480991 Email: premiseranchico@canarabank.com;

Web: http://www.canarabank.com

CORRIGENDUM

Ref.No. RNCO/GAS/CHATRA/ON 651/2024-2025/MKS Date: 27.01.2025			
S.no.	Description	EXISTING	AMMEDED
ITEM NO. 2 OF FURNISHING BOQ	FULL HEIGHT SOLID PARTITION Providing and Fixing in position full height solid partition 64mm thk. as indicated in the drawing made out of aluminium hollow sections of 50mmx25mm size (tolerance +- 1mm) 1.5 mm thk. (tolerance +- 10%) of JINDAL / INDAL/HINDALCO/EQUIVALENT make as internal framed structure placed horizontally & vertically in 600mm x 600 mm center to center or as directed by the Architect. The alternate corner vertical members of the partition shall be taken upto the ceiling level (payment shall be made for the partition measured below the false ceiling securely with help of suitable cleats/extra memberas per required /instructed. Framework shall be fixed with 6 mm thick ply (IS - 710) of approved make on both sides finished as per following specifications. The Partition shall be finished with 0.8 mm thick laminate of approved shade and make on both the sides. DOOR-Providing and fixing Solid Core wooden Flush Door Shutter (IS - 2202) of 35 mm thk. finished both side with 0.8 mm thk. approved colour laminate to be fixed to Wooden frame made of 19mm ply. The rate shall be inclusive of fitting and fixing of hinges, Godrej make door closer, door stopper, screws, Godrej ma	QUANTITY MISSING IN BOQ	QUANTITY- 60SQFT

Date: 04.02.2025 Place: RANCHI

SENIOR MANAGER