



Exit fan

Cashier's Table



Layout is Approved Subject to compliance of observations made vide Ref. No. 1028/2024-25 Date: 29/06/2024

Note -
1. All Columns Are Inside the wall's need to Re-measure and Mark the columns according to the Site after the demolishing of existing Walls (strong room, Record room and Toilet)

कृते कनरा बँके / For CANARA BANK
मंडल प्रबंधक / Divisional Manager
सा.प्र. विभाग, प्र.का., बेंगलूर - 560 004
G.A. Wing, H.O., BENGALURU - 560 004

Carpet Area - 1,974.50 + 97.50 = 2,072.00sqft